

MEMBER ALERT



Shipowners Claims Bureau, Inc., Manager
One Battery Park Plaza 31st Fl., New York, NY 10004 USA
Tel: +1 212 847 4500
Fax: +1 212 847 4599

<https://www.american-club.com>

JANUARY 19, 2022

GOOD CATCH UPDATES: CORROSION OF TWIST LOCK FOUNDATIONS AND PAD EYES

Your Managers are pleased to present the latest instalment of the Club's *Good Catch* initiative:

- *Corrosion of Twist Lock Foundations and Pad Eyes* in [English](#), [new](#) and [traditional Mandarin](#).

GOOD CATCH from The American Club
Corrosion of Twist Lock Foundations and Pad Eyes

Description A general cargo vessel had been modified to carry containers on the cargo hatches. Various twist lock foundations and pad eyes had been welded to the hatch covers to secure containers. While the vessel was in port preparing to offload and load containers, the newly arrived Chief Officer noticed that many of the twist lock foundations and pad eyes were significantly corroded. He raised his concern with the Master. They jointly inspected them and found them likely be greatly due to the excessive corrosion. The Master called the vessel management company who made arrangements to offload the remaining containers, find a lay berth and make repairs. The vessel spent 2 days at the lay berth and then resumed its schedule without incident. The incident was written up as a near miss by the Chief Officer who correctly felt that several of the fittings and pad eyes were on the verge of falling and containers could have subsequently been lost or seriously damaged.

Actual Damages The delay cost the vessel management company just under \$27,000 in berth fees plus an additional \$18,000 to remove and replace 25 heavily corroded twist lock foundations and 38 heavily corroded pad eyes. During that time, the crew worked to preserve the remaining twist lock foundations and pad eyes.

GOOD CATCH Corrosion of Twist Lock Foundations and Pad Eyes January 2022

Potential Damages Had the repairs not been made and the vessel experienced the heavy weather that had been predicted on their intended route, it is possible that several containers would have been lost overboard or damaged. Costs for the containers could have exceeded \$50,000 per container not including any damage to the vessel from unsecured containers.

Prevention

- Mariners should raise safety concerns when they see something that they know or suspect is not safe.
- Twist lock foundations and lashing gear pad eyes should be inspected regularly to ensure they are not damaged or corroded.
- Mariners should be especially vigilant regarding new or non-routine operations such as loading and carrying containers on general cargo vessels.

When you identify a hazard before something goes wrong... **it's a Good Catch.**

When you stop an operation before something bad happens... **it's a Good Catch.**

When you recognize and say something about corrosion that may have weakened the ability of twist lock foundations and pad eyes to properly function... **that's a Good Catch, too!**

The American Club would like to specially thank [Kobayashi Maritime Consulting, LLC](#) for their contribution to this document.

THE AMERICAN CLUB

American Steamship Owners Mutual Protection & Indemnity Association, Inc.

Shipowners Claims Bureau, Inc., Manager

New York
Tel: +1 212 847 4500 Fax: +1 212 847 4599
Email: info@americanclub.com Web: www.americanclub.com

Manila
Tel: +1 346 229 9800
Email: manila@americanclub.com

Shipowners Claims Bureau (P) Ltd.

London
Tel: +44 20 7593 6000
Email: scb@americanclub.com

Shipowners Claims Bureau (Hellas), Inc.

Piraeus
Tel: +30 210 429 4500 Fax: +30 210 429 4187
Email: piraeus@americanclub.com

SCB Management Consulting Services, Ltd.

Hong Kong
Tel: +852 3932 2100
Email: hk@americanclub.com

SCB Management Consulting (China) Co., Ltd.

Shanghai
Tel: +86 21 2366 6000 Fax: +86 21 2366 6100
Email: shanghai@americanclub.com

As a reminder, all *Good Catch* alerts and animations are posted at the Club's website at:

https://www.american-club.com/page/good_catch

Your Managers recommend that Members take note of this information and be guided accordingly.