

# MEMBER ALERT



Shipowners Claims Bureau, Inc., Manager  
One Battery Park Plaza 31<sup>st</sup> Fl., New York, NY 10004 USA  
Tel: +1 212 847 4500  
Fax: +1 212 847 4599


<https://www.american-club.com>

DECEMBER 22, 2021

## GOOD CATCH UPDATE: *WORKLOAD DISTRACTION RESULTS IN A GROUNDING*

Your Managers are pleased to present the latest instalments of the Club's *Good Catch* initiative

- *Workload Distraction Results in a Grounding* in [English](#), [new](#) and [traditional](#) Mandarin.



**GOOD CATCH** from The American Club  
**Workload Distraction Results in a Grounding**

**Description**  
A general cargo vessel was underway in ballast to its next port to load cargo. The port call was a last minute change that required new paper charts to be delivered to the vessel urgently before departure. The charts had just been received onboard the vessel minutes before the vessel's departure. Although equipped with an Electronic Chart Display and Information System (ECDIS), the policy on this vessel at the time was to use paper charts as the primary means for navigation.

The Second Officer was responsible for drafting the passage plan and presenting it to the Master for final approval. The last-minute change to an unfamiliar port, and the late arrival of the paper charts to the vessel, resulted in a passage plan not having been fully developed prior to departure. The Master decided to review and approve the passage plan in increments to avoid what he thought would be unnecessary delays.


The Second Officer assumed the watch at 1200 the day after the vessel got underway. He planned to complete the passage plan for the remainder of the voyage and also update the new navigation charts with the latest corrections while on watch.

After completing the draft passage plan, the Second Officer began work on chart corrections while continuing to navigate the vessel. His multi-tasking abruptly ended when the vessel ran aground on a charted rock at 1530.

The investigation revealed that the Second Officer was significantly distracted from his primary watchstanding duties when he was working on the passage plan and updating the paper charts. These workload distractions caused him to initially miss a planned turn and later to incorrectly plot a fix on the chart. While that fix had been correctly taken and recorded in the log, he had incorrectly joined it to the chart track. Had it been correctly plotted, the Second Officer would have seen that the vessel was significantly off the intended track line and was at risk of grounding.

Further, the investigation revealed that the Second Officer's focus on the passage plan and navigation chart corrections led to a poorly executed watch relief at 1200 when he failed to review the passage plan that had been approved for that portion of the voyage. He had failed to identify the navigational hazards the vessel would encounter during the upcoming watch.

The investigators also determined that numerous requirements in the safety management system (SMS) had not been followed related to passage planning, bridge watchstanding procedures and navigation in restricted waters.



**GOOD CATCH** Workload Distraction Results in a Grounding December 2021

**Actual Injuries and Damage** The vessel remained hard aground for several hours until refloated by the rising tide. It was blown out of service and proceeded directly to a shipyard for a detailed damage assessment and repairs. Fortunately, there were no injuries to the crew or pollution.

**Potential Damages** This grounding and the resultant hull damage could have been substantially worse. The hull could have been penetrated and flooded in part. A major pollution incident could have been caused.

**Prevention**

- Crews should be reminded that the primary responsibility of the Officer of the Watch is the safe navigation of the vessel.
- The watch relief process is critically important. The incoming Officer of the Watch needs to know and verify the vessel's location, course and speed. But he or she also needs to identify potential hazards the vessel will likely encounter during that watch before assuming the watch.
- Distractions while on watch should be eliminated or minimized to the maximum extent possible. Those distractions can include other legitimate work such as updating charts, checking emails, catching up on other log entries, passage planning, etc. While all legitimate work, they should not be done while on watch.
- Passage plans should be developed, reviewed and approved in advance of departure. Additionally, they should be presented for review as a complete berth-to-berth plan to each portion of the voyage can be reviewed in context with the other portions.

When you identify a hazard before something goes wrong... **it's a Good Catch.**  
When you stop an operation before something bad happens... **it's a Good Catch.**  
When you recognize hazardous distractions to good watchstanding and eliminate them... **that's a Good Catch, too!**

The American Club would like to specially thank **Independent Marine Consulting, LLC** for their contribution to this document.



American Steamship Owners Mutual Protection & Indemnity Association, Inc.  
Shipowners Claims Bureau, Inc., Manager

<b>New York</b> tel: +1 212 847 4500 fax: +1 212 847 4599 email: <a href="mailto:info@americanclub.com">info@americanclub.com</a>	<b>Houston</b> tel: +1 281 233 9900 fax: +1 281 233 9901 email: <a href="mailto:info@americanclub.com">info@americanclub.com</a>	<b>London</b> tel: +44 20 7193 1900 fax: +44 20 7193 1901 email: <a href="mailto:info@americanclub.com">info@americanclub.com</a>	<b>Shanghai</b> tel: +86 21 2064 6200 fax: +86 21 2064 6100 email: <a href="mailto:info@americanclub.com">info@americanclub.com</a>	<b>Panama</b> tel: +507 201 429 4900 fax: +507 201 429 4917 email: <a href="mailto:info@americanclub.com">info@americanclub.com</a>	<b>Hong Kong</b> tel: +852 2963 2000 fax: +852 2963 2001 email: <a href="mailto:info@americanclub.com">info@americanclub.com</a>	<b>SCB Management Consulting Services, Ltd.</b> <b>Shanghai</b> tel: +86 21 2064 6200 fax: +86 21 2064 6100 email: <a href="mailto:info@americanclub.com">info@americanclub.com</a>
--	---	--	--	--	---	---

As a reminder, all *Good Catch* alerts and animations are posted at the Club's website at:

[https://www.american-club.com/page/good\\_catch](https://www.american-club.com/page/good_catch)

Your Managers recommend that Members take note of this information and be guided accordingly.