

MEMBER ALERT



Shipowners Claims Bureau, Inc., Manager
 One Battery Park Plaza 31st Fl., New York, NY 10004 USA
 Tel: +1 212 847 4500
 Fax: +1 212 847 4599

<https://www.american-club.com>

MARCH 2, 2022

GOOD CATCH UPDATE: *MOORING LINE SLACK AND DOWN THE HOLE*

Your Managers are pleased to present the latest instalments of the Club's *Good Catch* initiative:

- *Mooring Line Slack* in [English](#), [new](#) and [traditional](#) Mandarin; and
- *Down the Hole* in [English](#), [new](#) and [traditional](#) Mandarin.

GOOD CATCH from The American Club

Mooring Line Slack

Description
 A general cargo vessel was moored at a facility to offload its cargo with its port side to the dock. The vessel was using its standard mooring line configuration with bow and stern lines, a forward and an aft spring line and 2 breast lines. Anticipating that the vessel's draft would be decreasing as the cargo was being offloaded, the Chief Officer had instructed that some slack be left in the mooring lines. He did not specify how much slack and did not check the mooring lines himself. The weather was mild with winds blowing at approximately 12 knots and there was no appreciable current at that dock. Shortly after offloading began, a tank vessel passed by. The wake from the tank vessel caused the general cargo vessel to move pushing it into the dock then pulling it away from the dock while also sliding it forward. The movement was substantial due to the slack in the mooring lines. The mass of the vessel and the movement forward damaged the fendering system and created a series of scrapes along the vessel's hull. The mooring lines were not damaged nor were the bollards on the dock. However, several of the large rubber fenders were torn from their mounts. The investigation determined that the slack in the mooring lines was excessive for the circumstances and that the Chief Officer's attempt to save the crew some work by leaving the mooring lines was inappropriate. The investigation also concluded that the tank vessel passed by at a reasonable speed and a reasonable distance from the general cargo vessel.

Actual Injuries and Damage
 The damage was limited to the fender system on the dock and scrapes in the paint on the port side of the general cargo vessel. The unknown condition of the fender system prior to the incident created questions about whether the vessel was responsible for the damage or whether the fender system was in poor condition prior to the vessel arriving. The claim took over a year to resolve with the repairs and legal fees totaling over \$26,000.

AMERICAN CLUB GOOD CATCH Mooring Line Slack March 2022

Potential Injuries and Damage
 This incident could have been substantially worse. Had someone been standing or walking on the gangway at the time of the incident, they could have been seriously hurt. Although the mooring lines held as designed and intended, had one or more mooring lines parted, the vessel's movement could have easily caused hull damage significantly more extensive than the paint scrapes experienced.

Prevention
 • Mooring lines should always be conscientiously and diligently tended as cargo is loaded or offloaded, as the tide changes, and as wind and weather change.
 • Time-saving shortcuts such as stacking the mooring lines in anticipation of cargo being offloaded should only be considered after an assessment of the associated risks and should only ever be done incrementally.
 • The mooring plan should consider the likelihood of other vessels passing by in close proximity and the mooring configuration should be adjusted accordingly.

When you identify a hazard before something goes wrong... **it's a Good Catch.**
 When you stop an operation before something bad happens... **it's a Good Catch.**
 When you recognize that mooring lines should not be slacked in anticipation of a draft change... **that's a Good Catch, too!**

The American Club would like to specially thank [Independent Maritime Consulting, LLC](#) for their contribution to this document.

AMERICAN CLUB

American Steamship Owners Mutual Protection & Indemnity Association, Inc.
 Shipowners Claims Bureau, Inc., Manager
 New York: Tel: +1 212 847 4500 Fax: +1 212 847 4599
 Houston: Tel: +1 281 223 9800
 Shipowners Claims Bureau (UK) Ltd, London: Tel: +44 20 7152 1900
 Shipowners Claims Bureau (Hk), Inc., P.O. Box: Tel: +852 3023 4900 Fax: +852 250 429 4987
 SCB Management Consulting Services, Ltd, Hong Kong: Tel: +852 3002 2200
 SCB Management Consulting (China) Co., Ltd, Shanghai: Tel: +86 21 2866 5000 Fax: +86 21 2866 4100

DOWN THE HOLE?

UNSAFE CONDITION NEAR MISS/ POTENTIAL ACCIDENT ACCIDENT AVERTED!

GOOD CATCH! TIME SPENT SETTING UP A SAFETY GUARD RAIL CAN MEAN AN ACCIDENT AVERTED!

AMERICAN CLUB

As a reminder, all *Good Catch* alerts and animations are posted at the Club's website at:

https://www.american-club.com/page/good_catch

Your Managers recommend that Members take note of this information and be guided accordingly.