

## GOOD CATCH from The American Club

## **Mooring Line Slack**

## **Description**

A general cargo vessel was moored at a facility to offload its cargo with its port side to the dock. The vessel was using its standard mooring line configuration with bow and stern lines, a forward and an aft spring line and 2 brest lines.

Anticipating that the vessel's draft would be decreasing as the cargo was being offloaded, the Chief Officer had instructed that some slack be left in the mooring lines. He did not specify how much slack and did not check the mooring lines himself. The weather was mild with winds blowing at approximately 1-2 knots and there was no appreciable current at that dock.

Shortly after offloading began, a tank vessel passed by. The wake from the tank vessel caused the general cargo vessel to move pushing it into the dock then pulling it away from the dock while also sliding it forward. The movement was substantial due to the slack in the mooring lines.

The mass of the vessel and the movement forward damaged the fendering system and created a series of scrapes along the vessel's hull. The mooring lines were not damaged nor were the bollards on the dock. However, several of the large rubber fenders were torn from their mounts.

The investigation determined that the slack in the mooring lines was excessive for the circumstances and that the Chief Officer's attempt to save the crew some work tending the mooring lines was inappropriate. The investigation also concluded that the tank vessel passed by at a reasonable speed and a reasonable distance from the general cargo vessel.

## Actual Injuries and Damage

The damage was limited to the fender system on the dock and scrapes in the paint on the port side of the general cargo vessel. The unknown condition of the fender system prior to the incident created questions about whether the vessel was responsible for the damage or whether the

fender system was in poor condition prior to the vessel arriving. The claim took over a year to resolve with the repairs and legal fees totaling over \$96,000.















# Potential Injuries and Damage

This incident could have been substantially worse. Had someone been standing or walking on the gangway at the time of the incident, they could have been seriously hurt. Although the mooring lines held as designed and intended, had one or more mooring lines parted, the vessel's movement could have easily caused hull damage significantly more

extensive than the paint scrapes experienced.

## **Prevention**

- ★ Mooring lines should always be conscientiously and diligently tended as cargo is loaded or offloaded, as the tide changes, and as wind and weather change.
- ★ Time-saving shortcuts such as slacking the mooring lines in anticipation of cargo being offloaded should only be considered after an assessment of the associated risks and should only ever be done incrementally.
- ★ The mooring plan should consider the likelihood of other vessels passing by in close proximity and the mooring configuration should be adjusted accordingly.

When you identify a hazard before something goes wrong...

When you stop an operation before something bad happens...

When you recognize that mooring lines should not be slacked in anticipation of a draft change...

it's a Good Catch. it's a Good Catch.

### that's a Good Catch, too!

The American Club would like to specially thank <u>Independent Maritime Consulting, LLC</u> for their contribution to this document.





American Steamship Owners Mutual Protection & Indemnity Association, Inc.

#### Shipowners Claims Bureau, Inc., Manager

#### **New York**

tel +1 212 847 4500 fax +1 212 847 4599 email info@american-club.com web www.american-club.com

#### Houston

tel +1 346 223 9900 email claims@american-club.com

#### Shipowners Claims Bureau (UK) Ltd.

#### London

tel +44 20 7709 1390 email <u>claims@scb-uk.com</u>

#### Shipowners Claims Bureau (Hellas), Inc.

#### Piraeus

tel +30 210 429 4990 fax +30 210 429 4187 email claims@scb-hellas.com

#### SCB Management Consulting Services, Ltd.

#### **Hong Kong**

tel +852 3905 2150 email <u>hkinfo@scbmcs.com</u>

#### SCB Management Consulting (China) Co., Ltd.

#### ihanghai

tel +86 21 3366 5000 fax +86 21 3366 6100 email <u>claims@scbmcs.com</u>